

<h1>Technical Bulletin</h1>	Model 6 Cyl.	Group 0
Subject Removal of Fuses During Transport or Storage of Vehicle	Part Identifier 0101	Number 9602

ATTENTION: Service Manager / Service Technician

Models Affected: *All 911 Carrera (993) and 911 Turbo (993)*

Concern: Removal of fuses to reduce current draw on the vehicle battery during transportation or storage.

General Information: Starting with October 1995 production, all 911 models are shipped to the dealer with the following fuses removed from the vehicle's central electric board (CEB) :

Fuse	Rating	Circuit
11	7.5 amp	Front and rear lid lights and glove box light
12	15 amp	Clock, diagnosis and alarm LED
13	30 amp	Cabriolet top / Sliding roof
29	7.5 amp	Interior lights and infrared sensing
38	15 amp	Radio

Repair Information: When receiving a new vehicle for dealer inventory, the vehicle's CEB should be checked to assure the appropriate fuses are removed and stored in a plastic bag in the glove compartment, and the interior light switches are set to the "off" position.

At the time of retail sale, the fuses must be placed back in their appropriate locations in the CEB. The radio code and time clock must also be reset.

Note: Advise Sales personnel of this procedure.

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1996 Porsche Cars North America, Inc.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____	_____
Distribution	Asst. manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____	_____
Routing							

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.