

# Technical Bulletin

Model  
6 Cyl.

Group  
5

**Subject:** Care of Inside Painted Surfaces of  
Front and Rear Lid

**Part Identifier**  
L . . .

**Number**  
9401

**ATTENTION:** Service Manager / Service Technician

**Models Affected:** *911 Carrera 1995-on*

**General Information:** With the beginning of 1995 production, the front and rear lids of the 911 Carrera received a reduced paint thickness on the inside surfaces only. The inside surfaces of the front and rear lids are also not clear coated.

**IMPORTANT:** When cleaning the inside surfaces of the front and rear lids, use only a non-petroleum cleaner such as mild soap or shampoo. Using petro-chemical cleaners (stain remover/tar remover) in an **extended application** may result in some discoloration or removal of the paint. Stubborn dirt or soil may be removed with mineral spirits used briefly. Afterwards, use mild soap and water to remove any petroleum based residues.

The corrosion protection of the front and rear lid is **NOT** negatively influenced through the reduced paint thickness or lack of clear coat.

