

Technical Bulletin

Model
6 Cyl.

Group
1

Subject:

Oil Return Tubes

Part Identifier
1546

Number
9405

ATTENTION: Service Manager / Service Technician

Models Affected: *911 Carrera 1995*

General Information: Although currently not reflected in the parts microfiche, the oil return tubes for the 911 Carrera Model Year 1995 are identical to the oil return tubes used in the 911 Carrera 2/4.

Should replacement of an oil return tube become necessary, two-piece oil return tubes, Part Number 930 107 040 01, are to be used for "engine in car" repairs.

This information will be reflected in the next spare parts fiche update.

Parts Information:

Description


Part Number

1 - piece oil return tube

901 107 351 01

2 - piece oil return tube

930 107 040 01



P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

